## Checklist: Slip, trip, and fall hazards

| Slip, Trip and Fall Hazard Description   | Cal/OSHA Citation   |
|--|---|
| Damaged concrete walking surface on stairway landings  | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Broken, damaged, chipped or missing floor tiles, damaged floor area,<br>uneven floor surface               | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Damaged, chipped or peeling linoleum where it meets floor tiles, uneven floor surface                      | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Damaged floor tiles at transition point between two rooms<br>(concrete to tile)                            | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Missing floor drain cover  | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Metal electrical conduits on roof in designated walkway  | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Water pipes on floor in walkway locations  | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Water leaking on floor, slip/fall hazard   | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Oil leaking on floor   | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Loose bolts on ladder  | §3277(i)-Fixed Ladders<br>http://www.dir.ca.gov/title8/3277.html                    |
| Decay present on wooden stepladder   | §3276(e)(1)(2)&(3)-Portable Ladders<br>http://www.dir.ca.gov/title8/3276.html       |
| Crossover work platforms have no mid rails   | §3210(a)-Guardrails At Elevated Locations<br>http://www.dir.ca.gov/title8/3210.html |
|  | §3209(a)-Standard Guardrails<br>http://www.dir.ca.gov/title8/3209.html              |
| Pipes project into walkway   | §3273(a)-Working Area<br>http://www.dir.ca.gov/title8/3273.html                     |
| Written protocols do not include procedures or training to ensure floor is dry prior to removal of signage | N/A   |



© BSI Group