

Kitemark™ Certificate

This is to certify that:

Newcastle Accident Repair Ltd
Unit 16
63a Castlewellan Road
Newcastle
BT33 0JX
United Kingdom

Holds Certificate Number:

KM 823590

In respect of:

BS 10125:2022

Vehicle Damage Repair

This issues the right and licence to use the Kitemark in accordance with the Kitemark Terms and Conditions governing the use of the Kitemark, as may be updated from time to time by BSI Assurance UK Ltd (the "Conditions"). All defined terms in this Certificate shall have the same meaning as in the Conditions.

The use of the Kitemark is authorized in respect of the Product(s) detailed on this Certificate provided at or from the above address.

For and on behalf of BSI:



Shahm Barhom, Group Product Certification Director

First Issued: 2025-03-27

Latest Issue: 2025-03-27



Page: 1 of 2

...making excellence a habit.™

No. KM 823590

Location	Registered Activities
Newcastle Accident Repair Ltd Unit 16 63a Castlewellan Road Newcastle BT33 0JX United Kingdom	BS 10125:2022 Automotive Services Vehicle Damage Repair This Kitemark Certificate covers the process of vehicle damage repair for the following capability tasks: C0.0 Repair preparation C1 Dent removal C2 Plastic repair C3 Refinishing C4 Hot joining steel C6 Cold joining C7 Autoglazing C8 Body alignment C9 Road wheels C10 Steering and suspension C11 ADAS C12 SRS C13 Low voltage electrics C14 Mechanical systems C15 Internal combustion engine C16 Mild and high voltage systems

First Issued: 2025-03-27

Latest Issue: 2025-03-27